

Final Reclamation Inspection

March 8, 2022

Operator: NOBLE ENERGY INC - #100322

Location ID: 332402

Inspection Document #: 697503788

Weld County, CO

NENW Section 34 T5N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: BOULTER #3-34
Location ID: 332402



Photo 1. Google Earth aerial imagery from 6/22/2004. Photo illustrates the well location and new access road.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697503788

Inspection Photos
Location Name: BOULTER #3-34
Location ID: 332402



Photo 2. Google Earth aerial imagery from 6/11/2021 post plugging operations. Photo illustrates the well location access road remains and has not been reclaimed.



Inspection Photos
Location Name: BOULTER #3-34
Location ID: 332402



Photo 3. Photo taken north of the well location, facing South. Photo illustrates the well location does not appear to be reflective of reference area vegetative levels. COGCC Staff did not go to the location because of cattle with calves.



Inspection Photos
Location Name: BOULTER #3-34
Location ID: 332402



Photo 4. Well location reference vegetative photo taken north of the location, facing East.



Inspection Photos
Location Name: BOULTER #3-34
Location ID: 332402



Photo 5. Photo taken from the associated offsite tank battery, facing South. Photo illustrates the tank battery is not reflective of reference area vegetation. Most of the tank battery is bare or sparse vegetation.



Inspection Photos
Location Name: BOULTER #3-34
Location ID: 332402



Photo 6. Tank battery reference vegetative photo taken adjacent to the location. Tank battery within the red-dashed line.

