

Inspection Photos
Location Name: EHN 3-20
Location ID: 319660



Photo 1 WH sign



Photo 2 WH

Inspection Photos
Location Name: EHN 3-20
Location ID: 319660



Photo 3 wellsite



Photo 4 no electric motor or gas engine to power PJ

Inspection Photos
Location Name: EHN 3-20
Location ID: 319660



Photo 5 Electric power cut at ground level