

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS-67S96W /26SWNW.

Location ID: 334702



Photo #6159 from entrance to location.



Photo #6160 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS-67S96W /26SWNW.

Location ID: 334702



Photo #6161 Location lacks stabilization.



Photo #6162 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS-67S96W /26SWNW.

Location ID: 334702



Photo #6163 Location lacks stabilization.



Photo #6164 Insufficient tracking BMP at entrance to location.