

Inspection Photos
Location Name: Anderson 33-34
Location ID: 309912



Photo 1: Wellhead Sign




Photo 2: Wellhead

Inspection Photos
Location Name: Anderson 33-34
Location ID: 309912



Photo 3: Unused Equipment




Photo 4: Tank Battery Sign



Inspection Photos
Location Name: Anderson 33-34
Location ID: 309912



Photo 5: Centralized Tank Battery



Photo 6: No calibration card displayed

