

Inspection Photos
Location Name: Piccoli A #1
API: 05-067-07186



Piccoli A #1 location photo.



"Pump to line" system (right side of photo) has recently taken the place of the vertical heated separator.

Inspection Photos
Location Name: Piccoli A #1
API: 05-067-07186



Illegible sign near eastern PBV.



Recently installed perimeter berm.