

# Final Reclamation Inspection

March 14, 2022

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 328643

Inspection Document #: 697503812

Weld County, CO

NESE Section 12 T3N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation**  
**Commission**

Department of Natural Resources

Inspection Photos

Location Name: OPATRIL P #12-22D

Location ID: 328643



**Photo 1.** Photo taken north of the well location, facing South. Photo illustrates the field has not been planted and is fallow cropland. It appears the field has been fallow since 2015.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 697503812



Inspection Photos

Location Name: OPATRIL P #12-22D

Location ID: 328643



**Photo 2.** Photo taken from the associated offsite tank battery, facing Northwest. Photo illustrates the tank battery has perennial vegetation established throughout, unlike the well location and well location reference areas.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 697503812






**Photo 3.** Photo taken from the associated offsite tank battery, facing Southeast. See comments under Photo 2.



Inspection Photos

Location Name: OPATRIL P #12-22D

Location ID: 328643



**Photo 4.** 1984 aerial imagery illustrates the well location and tank battery access roads were pre-existing prior to oil and gas.