

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S95W /31SWSE

Location ID: 334917



Photo #6243 from entrance to location.



Photo #6244 load line open ended.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S95W /31SWSE

Location ID: 334917



Photo #6245 Location lacks stabilization.



Photo #6246 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S95W /31SWSE

Location ID: 334917



Photo #6247 Insufficient tracking BMP at entrance to location.