

**RIO MESA RESOURCES INC
GOVERNMENT 61N102W 1SW SW
Location # 315092**



Tank battery doesn't meet Rule 605.e..



Base of berm is marshy.

**RIO MESA RESOURCES INC
GOVERNMENT 61N102W 1SW SW
Location # 315092**



Damaged tank labels.



Damaged tank labels.

**RIO MESA RESOURCES INC
GOVERNMENT 61N102W 1SW SW
Location # 315092**



Sign installed with API #

RIO MESA RESOURCES INC
GOVERNMENT 61N102W 1SW SW
Location # 315092



**RIO MESA RESOURCES INC
GOVERNMENT 61N102W 1SW SW
Location # 315092**



**RIO MESA RESOURCES INC
GOVERNMENT 61N102W 1SW SW
Location # 315092**



Sediment coming off hillside behind tank battery berm and collecting sediment and stormwater in berm.



Subsidence of tank ground base. Base of berm is marshy.

**RIO MESA RESOURCES INC
GOVERNMENT 61N102W 1SW SW
Location # 315092**



Storm water damage of access road and moving across south end of location.

**RIO MESA RESOURCES INC
GOVERNMENT 61N102W 1SW SW
Location # 315092**



Stained well head and cellar cover.

**RIO MESA RESOURCES INC
GOVERNMENT 61N102W 1SW SW
Location # 315092**



Stained ground surfaces.



Stained ground surfaces.