

**Inspection Photos**  
**Location Name: Horsetail 30 CPB**  
**Location ID: 436612**



**Photo 1 – Tank Battery**



**Photo 2 – Tank Battery**

**Inspection Photos**  
**Location Name: Horsetail 30 CPB**  
**Location ID: 436612**



**Photo 3 – VRTs**




**Photo 4 – Water Tanks**



**Inspection Photos**  
**Location Name: Horsetail 30 CPB**  
**Location ID: 436612**



**Photo 5 – Tank Battery Sign**



**Photo 6 – Unmarked Riser**



**Inspection Photos**  
**Location Name: Horsetail 30 CPB**  
**Location ID: 436612**



**Photo 7 – ECD**



**Photo 8 – LACTs**





**Inspection Photos**  
**Location Name: Horsetail 30 CPB**  
**Location ID: 436612**



**Photo 9 – Water LACTS**



**Photo 10 – Various Unmarked Risers, Tags have faded/Weathered away**



**Inspection Photos**  
**Location Name: Horsetail 30 CPB**  
**Location ID: 436612**



**Photo 11 – Various Unmarked Risers, Tags have faded/Weathered away**



**Photo 12 – Various Unmarked Risers, Tags have faded/Weathered away**



**Inspection Photos**  
**Location Name: Horsetail 30 CPB**  
**Location ID: 436612**



**Photo 13 – Various Unmarked Risers, Tags have faded/Weathered away**




**Photo 14 – Production Equipment**

**Inspection Photos**  
**Location Name: Horsetail 30 CPB**  
**Location ID: 436612**



**Photo 15 – Flare**



**Photo 16 – Unmarked Riser**



**Inspection Photos**  
**Location Name: Horsetail 30 CPB**  
**Location ID: 436612**



**Photo 17 – Various Unmarked Risers, Tags have faded/Weathered away. Unused Chemical Tank**



**Photo 18 – Various Unmarked Risers, Tags have faded/Weathered away. Unused Chemical Tank**

**Inspection Photos**  
**Location Name: Horsetail 30 CPB**  
**Location ID: 436612**



**Photo 19 – Stained Soil**



**Photo 20 – Compressor**





**Inspection Photos**  
**Location Name: Horsetail 30 CPB**  
**Location ID: 436612**



**Photo 21 – Heater Treaters**



**Photo 22 – Heater Treaters**

**Inspection Photos**  
**Location Name: Horsetail 30 CPB**  
**Location ID: 436612**



**Photo 23 – Various Unmarked Risers, Tags have faded/Weathered away**



**Photo 24 – Production Equipment**