

Inspection Photos

March 15, 2022

Operator: TEP Rocky Mountain- #96850

Location ID: 335547

Location Name: GENTRY-66S92W /17SESW

Inspection Document #: 702800037

Garfield County, CO

SESW Section 17 T6S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: GENTRY-66S92W /17SESW
Location ID: 335547



Photo 1. Photo taken from the Location entrance in the northeast shows an overview of the Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800037

Inspection Photos
Location Name: GENTRY-66S92W /17SESW
Location ID: 335547



Photo 2. Photo taken from the northwest of the tank battery shows an unknown substance below the tank valve.



Photo 3. Photo taken from the north of the tank battery shows potentially impacted fluids throughout the secondary containment area of the tank battery.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800037

Inspection Photos
Location Name: GENTRY-66S92W /17SESW
Location ID: 335547



Photo 4. Photo taken from the well area shows BMPs to prevent wildlife access to the well cellars were missing or insufficient.

Inspection Photos
Location Name: GENTRY-66S92W /17SESW
Location ID: 335547



Photo 5. Photo taken from the east of the Location at the top of the cut slope shows a straw wattle has been installed to prevent run on.



Photo 6. Photo taken from the southeast of the Location shows unstable soils of the cut slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800037

Inspection Photos
Location Name: GENTRY-66S92W /17SESW
Location ID: 335547



Photo 7. Photo taken from the eastern interim areas facing southeast. Presently, it appears that interim areas are dominated by bare ground and annual weeds. A follow up inspection during the growing season is necessary to properly assess interim reclamation.



Photo 8. Photo taken from the northern interim areas facing east. See additional comments under Photo 7.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800037