

Inspection Photos
Location Name: Razor 25B PAD
Location ID: 436427



Photo 1 – Tank Battery

Photo 2 – Tank Batter Sign

Inspection Photos
Location Name: Razor 25B PAD
Location ID: 436427



Photo 3 – ECD



Photo 4 – Production Equipment

Inspection Photos
Location Name: Razor 25B PAD
Location ID: 436427



Photo 5 – Heater Treaters



Photo 6 – Compressor – Drain Pit missing Labels

Inspection Photos
Location Name: Razor 25B PAD
Location ID: 436427



Photo 7 – Wellheads



Photo 8 – Gas Lift Injection Meter House

Inspection Photos
Location Name: Razor 25B PAD
Location ID: 436427



Photo 9 – Wellheads