

Inspection Photos  
Location Name: Razor 22D PAD  
Location ID: 430695



Photo 1 – Signs at Entrance

Photo 2 – Methanol Tank

Inspection Photos  
Location Name: Razor 22D PAD  
Location ID: 430695



Photo 3 – 2208B Wellhead – Unmarked Riser



Photo 4 – Well Sign



**Inspection Photos**  
**Location Name: Razor 22D PAD**  
**Location ID: 430695**



**Photo 5 – Unused Well Parts at 2208B**



**Photo 6 – 2207 Wellhead – Unmarked Riser and Stained Soil**

Inspection Photos  
Location Name: Razor 22D PAD  
Location ID: 430695



Photo 7 – 2207A Well Sign



Photo 8 – 2703A Wellhead – Riser



**Inspection Photos**  
**Location Name: Razor 22D PAD**  
**Location ID: 430695**



**Photo 9 – 2703A – Rod and Riser**



**Photo 10 – 2703A Wellhead Sign**

**Inspection Photos**  
**Location Name: Razor 22D PAD**  
**Location ID: 430695**



**Photo 11 – 2712 Wellhead**



**Photo 12 – 2712H Wellhead Sign**



**Inspection Photos**  
**Location Name: Razor 22D PAD**  
**Location ID: 430695**



**Photo 13 – ECD and Flare**



**Photo 14 – Unmarked Risers on West side of Location**

**Inspection Photos**  
**Location Name: Razor 22D PAD**  
**Location ID: 430695**



**Photo 15 – VRU**



**Photo 16 – LACTS**



Inspection Photos  
Location Name: Razor 22D PAD  
Location ID: 430695



Photo 17 – Water Tanks



Photo 18 – Crude Oil Tanks

**Inspection Photos**  
**Location Name: Razor 22D PAD**  
**Location ID: 430695**



**Photo 19 – Tank Battery Sign**



**Photo 20 – Production Equipment**



**Inspection Photos**  
**Location Name: Razor 22D PAD**  
**Location ID: 430695**



**Photo 21 – Unmarked Risers on North Side**



**Photo 22 – Unmarked Risers on North Side**

**Inspection Photos**  
**Location Name: Razor 22D PAD**  
**Location ID: 430695**



**Photo 23 – Unmarked Risers on North Side**



**Photo 24 – Unmarked Risers on North Side**



**Inspection Photos**  
**Location Name: Razor 22D PAD**  
**Location ID: 430695**



**Photo 25 – Heater Treaters**



**Photo 26 – Meter Sheds**