

Inspection Photos

March 15, 2022

Operator: TEP Rocky Mountain- #96850

Location ID: 335546

Location Name: Robinson C Pad

Inspection Document #: 702800041

Garfield County, CO

SENE Section 17 T6S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Robinson C Pad
Location ID: 335546



Photo 1. Photo taken from the Location entrance facing northeast shows an overview of the production areas.



Photo 2. Photo taken from the Location entrance facing northwest shows an overview of the production areas.

Inspection Photos
Location Name: Robinson C Pad
Location ID: 335546



Photo 3. Photo taken from the well area shows BMPs to prevent wildlife access to the well cellars were missing or insufficient.



Photo 4. Refer to Photo 3 comments.



Inspection Photos
Location Name: Robinson C Pad
Location ID: 335546



Photo 5. Photo taken from the Location entrance facing east shows undesirable plant species/weeds (Kochia) established on the Location.



Photo 6. Photo taken from the east of the Location facing north shows a berm colonized by undesirable plant species/weeds (Kochia).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800041

Inspection Photos
Location Name: Robinson C Pad
Location ID: 335546



Photo 7. Photo taken from the production area adjacent to the wells shows storage of unnecessary equipment on Location.



Inspection Photos
Location Name: Robinson C Pad
Location ID: 335546



Photo 8. Photo taken from the eastern production area shows an unmarked anchor.



Inspection Photos
Location Name: Robinson C Pad
Location ID: 335546



Photo 9. Photo taken from the northern interim area facing west shows the area is dominated by bare ground.



Photo 10. Refer to Photo 9 comments.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800041

Inspection Photos
Location Name: Robinson C Pad
Location ID: 335546



Photo 11. Photo taken from the western interim area facing south shows the area is colonized by the annual plant, Kochia with large patches of bare ground.



Photo 12. Photo taken from the western interim area facing northeast shows the area dominated by bare ground with sparse establishment of perennial grasses.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800041

Inspection Photos
Location Name: Robinson C Pad
Location ID: 335546



Photo 13. Photo taken from the northern interim area shows bare ground and the establishment of the Colorado State noxious weed, Russian thistle.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800041

Inspection Photos
Location Name: Robinson C Pad
Location ID: 335546



Photo 14. Photo taken from the northeast of the Location shows eastern slopes colonized by the annual plant, Kochia with little perennial plant establishment.




Photo 15. Refer to Photo 14 comments.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800041

Inspection Photos
Location Name: Robinson C Pad
Location ID: 335546



Photo 16. Photo taken from the west of the Location shows degradation occurring in the form of rill erosion as water flows into a stormwater ditch.



Photo 17. Refer to Photo 16 comments.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800041

Inspection Photos
Location Name: Robinson C Pad
Location ID: 335546



Photo 18. Photo taken from the west of the Location shows degradation occurring in the form of rill erosion as water flows into a stormwater ditch.



Inspection Photos
Location Name: Robinson C Pad
Location ID: 335546



Photo 19. Photo taken from the west of the Location shows degradation occurring in the form of rill erosion occurring on unprotected slopes.



Photo 20. Refer to Photo 19 comments.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800041

Inspection Photos
Location Name: Robinson C Pad
Location ID: 335546



Photo 21. Photo taken from the north of the Location shows rutting occurring on the pad.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800041