

Inspection Photos
Location Name: Musser, B W "B" 6
Location ID: 312790



Photo 1. Overview of location taken facing west.



Photo 2. Ruts in access road.

