

Inspection Photos
Location Name: Musser No. 23
Location ID: 313161



Photo 1. Overview of location taken facing north.



Photo 2. Ruts in access road.



Inspection Photos
Location Name: Musser No. 23
Location ID: 313161



Photo 3. Sediment migrating off access road.



Photo 4. Sediment migrating off access road.

