

Inspection Photos
Location Name: Hosmer Harold W.
Location ID: 319676



Photo #1 Crude tanks.



Photo #2 P/W vault.

Inspection Photos
Location Name: Hosmer Harold W.
Location ID: 319676



Photo #3 Separator, meter, RTU.

Photo #4 Pell Head.

Inspection Photos
Location Name: Hosmer Harold W.
Location ID: 319676



Photo #5 Stained soil around the west crude tank, stains are on the north side.