

Inspection Photos  
Location Name: Sidney Strear #6  
Location ID: 318347



Photo 1 WH sign

Photo 2 WH, stained soil

**Inspection Photos**  
**Location Name: Sidney Strear #6**  
**Location ID: 318347**



**Photo 3 Pump Jack**

**Photo 4 ancillary equip.**

**Inspection Photos**  
**Location Name: Sidney Strear #6**  
**Location ID: 318347**



**Photo 5 Stained soil by WH**

**Photo 6 Leaking seal has been repaired/replaced**

**Inspection Photos**  
**Location Name: Sidney Strear #6**  
**Location ID: 318347**



**Photo 7 Stained cement at pump jack base where the seal was leaking.**