

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/22/2022

Submitted Date:

03/22/2022

Document Number:

696304060

**FIELD INSPECTION FORM**

Loc ID 444471 Inspector Name: PETRIE, ERICA On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96155  
Name of Operator: WHITING OIL & GAS CORPORATION  
Address: 1700 LINCOLN STREET SUITE 4700  
City: DENVER State: CO Zip: 80290

**Findings:**

- 14 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name  | Phone | Email                       | Comment    |
|---------------|-------|-----------------------------|------------|
| Smith, Sydney |       | ssmith@fundareresources.com | Regulatory |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name  | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 444462      | WELL | WO     | 07/13/2017  | LO         | 123-42637 | Razor 25P-2446 | WO          |
| 444464      | WELL | DG     | 11/22/2016  | LO         | 123-42639 | Razor 25P-2413 | WO          |
| 444467      | WELL | PR     | 09/01/2021  | OW         | 123-42641 | Razor 25P-2415 | PR          |
| 444468      | WELL | DG     | 11/22/2016  | LO         | 123-42642 | Razor 25P-2448 | WO          |
| 444469      | WELL | PR     | 09/01/2021  | OW         | 123-42643 | Razor 25P-2414 | PR          |
| 444476      | WELL | PR     | 09/01/2021  | OW         | 123-42648 | Razor 25P-2447 | PR          |
| 444480      | WELL | DG     | 10/20/2016  | LO         | 123-42652 | Razor 25P-2416 | WO          |

**General Comment:**

This is a Field Inspection ONLY, ANY Corrective Actions from Environmental Inspection 693700905 dated 12.30.2021

| Location   |   |        |                         |
|--|---|--------|-------------------------|
| Overall Good: <input checked="" type="checkbox"/>      |   |        |                         |
| <b>Signs/Marker:</b>                                   |   |        |                         |
| Type   | WELLHEAD  |        |                         |
| Comment:   | <a href="#">SE Wellhead 2448 missing Sign; see photos</a>             |        |                         |
| Corrective Action:                                     | <a href="#">Install sign to comply with Rule 605.d.</a>               |        | Date: <u>04/22/2022</u> |
| Emergency Contact Number:                              |   |        |                         |
| Comment:   | <input style="width: 100%;" type="text"/>                             |        |                         |
| Corrective Action:                                     | <input style="width: 100%;" type="text"/>                             |        | Date: _____             |
| <b>Good Housekeeping:</b>                              |   |        |                         |
| Type   | UNUSED EQUIPMENT  |        |                         |
| Comment:   | <a href="#">Unmarked Risers at TA Wellheads; see photos</a>           |        |                         |
| Corrective Action:                                     | <a href="#">Comply with Rule 606</a>                                  |        | Date: <u>03/25/2022</u> |
| Overall Good: <input type="checkbox"/>                 |   |        |                         |
| <b>Spills:</b>   |   |        |                         |
| Type   | Area  | Volume |                         |
| In Containment: No                                     |   |        |                         |
| Comment:   | <input style="width: 100%;" type="text"/>                             |        |                         |
| <input type="checkbox"/> Multiple Spills and Releases? |   |        |                         |
| <b>Fencing/:</b>                                       |   |        |                         |
| Type   | LOCATION  |        |                         |
| Comment:   | <a href="#">Barbed Wire</a>   |        |                         |
| Corrective Action:                                     |   |        | Date:                   |
| <b>Equipment:</b>                                      |   |        |                         |
| Type: Gas Meter Run                                    | # 3   |        | corrective date         |
| Comment:   |   |        |                         |
| Corrective Action:                                     |   |        | Date:                   |
| Type: Plunger Lift                                     | # 3   |        |                         |
| Comment:   |   |        |                         |
| Corrective Action:                                     |   |        | Date:                   |
| Type: Bradenhead                                       | # 7   |        |                         |
| Comment:   | <a href="#">Appear to be plumbed to surface</a>                       |        |                         |
| Corrective Action:                                     |   |        | Date:                   |
| Type: Other  | # 4   |        |                         |
| Comment:   | <a href="#">WO/TA Wellheads - Wellhead Drilled not yet Completed.</a> |        |                         |
| Corrective Action:                                     |   |        | Date:                   |
| <b>Venting:</b>  |   |        |                         |
| Yes/No   |   |        |                         |
| Comment:   |   |        |                         |

|                    |  |       |  |
|--------------------|--|-------|--|
| Corrective Action: |  | Date: |  |
|--------------------|--|-------|--|

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

| Inspected Facilities   |        |               |      |             |             |
|--|--------|---------------|------|-------------|-------------|
| Facility ID:   | 444462 | Type:         | WELL | API Number: | 123-42637   |
| Status:  | WO     | Insp. Status: | WO   |             |             |
| Idle Well  |        |               |      |             |             |
| Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned      Reminder: _____ |        |               |      |             |             |
| Comment: <span style="color: blue;">WO/TA - Well Drilled NOT yet Completed<br/>MIT - 10.09.2018</span>                   |        |               |      |             |             |
| Corrective Action: _____   |        |               |      |             | Date: _____ |
| Facility ID:   | 444464 | Type:         | WELL | API Number: | 123-42639   |
| Status:  | DG     | Insp. Status: | WO   |             |             |
| Idle Well  |        |               |      |             |             |
| Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned      Reminder: _____ |        |               |      |             |             |
| Comment: <span style="color: blue;">WO/TA - Well Drilled NOT yet Completed<br/>MIT - 09.14.2018</span>                   |        |               |      |             |             |
| Corrective Action: _____   |        |               |      |             | Date: _____ |
| Facility ID:   | 444467 | Type:         | WELL | API Number: | 123-42641   |
| Status:  | PR     | Insp. Status: | PR   |             |             |
| Producing Well   |        |               |      |             |             |
| Comment: <span style="color: blue;">PR</span>  |        |               |      |             |             |
| Corrective Action: _____   |        |               |      |             | Date: _____ |
| Facility ID:   | 444468 | Type:         | WELL | API Number: | 123-42642   |
| Status:  | DG     | Insp. Status: | WO   |             |             |
| Idle Well  |        |               |      |             |             |
| Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned      Reminder: _____ |        |               |      |             |             |
| Comment: <span style="color: blue;">WO/TA - Well Drilled NOT yet Completed<br/>MIT - 09.24.2018</span>                   |        |               |      |             |             |
| Corrective Action: _____   |        |               |      |             | Date: _____ |
| Facility ID:   | 444469 | Type:         | WELL | API Number: | 123-42643   |
| Status:  | PR     | Insp. Status: | PR   |             |             |
| Producing Well   |        |               |      |             |             |
| Comment: <span style="color: blue;">PR</span>  |        |               |      |             |             |
| Corrective Action: _____   |        |               |      |             | Date: _____ |
| Facility ID:   | 444476 | Type:         | WELL | API Number: | 123-42648   |
| Status:  | PR     | Insp. Status: | PR   |             |             |
| Producing Well   |        |               |      |             |             |
| Comment: <span style="color: blue;">PR</span>  |        |               |      |             |             |
| Corrective Action: _____   |        |               |      |             | Date: _____ |
| Facility ID:   | 444480 | Type:         | WELL | API Number: | 123-42652   |
| Status:  | DG     | Insp. Status: | WO   |             |             |

**Idle Well**

Purpose:  Shut In       Temporarily Abandoned      Reminder: \_\_\_\_\_

Comment: WO/TA - Well Drilled NOT yet Completed  
MIT - 01.14.2019

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           |                 | Gravel                  |                       |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402992242    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5701138">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5701138</a> |
| 696304061    | Photos               | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5701134">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5701134</a> |