

Final Reclamation Inspection

March 25, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 306403

Inspection Document #: 697503834

Weld County, CO

NESE Section 34 T7N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: GROVES #43-34
Location ID: 306403



Photo 1. Google Earth aerial imagery taken 12/11/2002 prior to the development of the Groves #43-34 location. Photo illustrates there is not a pre-existing road prior to the development of the location.

Inspection Photos
Location Name: GROVES #43-34
Location ID: 306403



Photo 2. Google Earth aerial imagery taken 6/19/2014 during active operations of the Groves #43-34 location. Photo illustrates an access road was in use for the location. This access road remains and has not been reclaimed per Rule 1004.

Inspection Photos
Location Name: GROVES #43-34
Location ID: 306403



Photo 3. Photo taken from the western access road, facing East. Photo illustrates the Operator has failed to reclaim the access road.

Inspection Photos
Location Name: GROVES #43-34
Location ID: 306403



Photo 4. Photo taken from the central access road, facing East. See comments under Photo 3.

Inspection Photos
Location Name: GROVES #43-34
Location ID: 306403



Photo 5. Photo taken from the well location, facing East. Photo illustrates Operator has performed final reclamation activities at the well location with the evidence of drill row and straw crimped mulch. The well location and associated access road are within cropland.

Inspection Photos
Location Name: GROVES #43-34
Location ID: 306403



Photo 6. Photo taken from the well location, facing West. See comments under Photo 5.

Inspection Photos
Location Name: GROVES #43-34
Location ID: 306403



Photo 7. Photo taken from the associated offsite tank battery, facing Northeast. Operator has performed final reclamation activities at the well location with the evidence of drill row and straw crimped mulch. Photo also illustrates that it appears the flowline has been removed and also reclaimed.

Inspection Photos
Location Name: GROVES #43-34
Location ID: 306403



Photo 8. Drone aerial imagery illustrates the access road that has not been reclaimed (red) and the flowline area (green).