

Inspection Photos  
Location Name: HSR-McHale 7-5A  
Location ID: 331366



Photo 1 WH sign.

Photo 2 WH

Inspection Photos  
Location Name: HSR-McHale 7-5A  
Location ID: 331366



Photo 3 TB sign.

Photo 4 TB

Inspection Photos  
Location Name: HSR-McHale 7-5A  
Location ID: 331366



Photo 5 LACT

Photo 6 Compressor

Inspection Photos  
Location Name: HSR-McHale 7-5A  
Location ID: 331366



Photo 7 VRU

Photo 8 Horiz. Heated Separators

Inspection Photos  
Location Name: HSR-McHale 7-5A  
Location ID: 331366



Photo 9 ECD

Photo 10 VRT

Inspection Photos  
Location Name: HSR-McHale 7-5A  
Location ID: 331366



Photo 11 Gas Meter Run