

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403002708

Date Received:
04/04/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10634

Name of Operator: P O & G OPERATING LLC

Address: 5847 SAN FELIPE SUITE 3200

City: HOUSTON State: TX Zip: 77057

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Welsh, Brian

brian.welsh@state.co.us

Quint, Craig

craig.quint@state.co.us

Nash, Charlotte

281.543.3606

charlotte_nash@pogresources.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 700600368

Inspection Date: 02/18/2022

FIR Submit Date: 02/23/2022

FIR Status: _____

Inspected Operator Information:

Company Name: P O & G OPERATING LLC

Company Number: 10634

Address: 5847 SAN FELIPE SUITE 3200

City: HOUSTON State: TX Zip: 77057

LOCATION - Location ID: 324818

Location Name: TALLMAN-618S45W Number: 23NWSE County: KIOWA

Qtrqr: NWSE Sec: 23 Twp: 18S Range: 45W Meridian: 6

Latitude: 38.475003 Longitude: -102.426008

FACILITY - API Number: 05-061-00 Facility ID: 212879

Facility Name: TALLMAN Number: 23-3

Qtrqr: NWSE Sec: 23 Twp: 18S Range: 45W Meridian: 6

Latitude: 38.475003 Longitude: -102.426008

CORRECTIVE ACTIONS:

1 CA# 159826

Corrective Action: Repair or install berms or other secondary containment devices per Rule 912.d.(1).

Date: 03/15/2022

Response: CA COMPLETED

Date of Completion: 02/28/2022

Operator
Comment: Work Completed

COGCC Decision: _____

COGCC
Representative:

2 CA# 159827

Corrective Action: Install or repair wildlife protection equipment.

Date: 02/28/2022

Response: CA COMPLETED

Date of Completion: 02/28/2022

Operator
Comment: Work completed

COGCC Decision: _____

COGCC
Representative:

3 CA# 159828

Corrective Action: Immediately to stop and clean up 24 hours to remove free fluids. 30-days to remove stained soil.

Date: 03/22/2022

Response: CA COMPLETED

Date of Completion: 02/28/2022

Operator
Comment: Work Completed

COGCC Decision: _____

COGCC
Representative:

4 CA# 159829

Corrective Action: Install sign to comply with Rule 605.a.

Date: 03/22/2022

Response: CA COMPLETED

Date of Completion: 02/28/2022

Operator
Comment: Work completed

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Charlotte Nash

Signed: _____

Title: Regulatory/Production

Date: 4/4/2022 7:57:07 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files