

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/29/2022

Submitted Date:

03/30/2022

Document Number:

689501346

FIELD INSPECTION FORMLoc ID 332754 Inspector Name: Brown, Kari On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10633

Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Address: 1801 CALIFORNIA STREET #2500

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		Inspections@civiresources.com	All inspections
Kelly, Luke		Lkelly@CiviResources.com	Environmental Supervisor

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
481318	SPILL OR RELEASE	AC	01/05/2022		-	Aristocrat Angus 63N65W 4SESW	EI

General Comment:

This is an environmental inspection of Remediation Project 21587/Spill ID 481318; follow up inspection of doc# 689501337. Any corrective actions from previous inspections that have not been addressed are still applicable.

There were no operator or contract environmental personnel on location at the time of this field inspection.

Photos attached to document site conditions.

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment: Spill ID 481318 remains open in the COGCC database. Document #402904666 reports date of discovery as 12/20/21. In accordance with Rule 912.a.(6) no later than 90 days after a Spill or Release is discovered Operator will submit a Form 19 Supplemental requesting closure.

Corrective Action: In accordance with Rule 912.a.(6) no later than 90 days after a Spill or Release is discovered Operator will submit a Form 19 Supplemental requesting closure. Closure of this spill can be requested with work proceeding under Remediation Project No 21587.

Date: 03/20/2022

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Lat _____

Long _____

Field Parameters:

Sample Location: _____

Comment: _____

Waste Management:

Type	Management	Condition	GPS (Lat)	(Long)
Comment	Appropriate stormwater BMPs have been installed around the soil stockpile observed in inspection #689501337.			
Corrective Action				Date: _____

Spill/Remediation:

Comment: _____

Corrective Action: _____

Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____

Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403000171	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5709751
689501347	Soil stockpile	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5709742