

Inspection Photos  
Operator: Logos  
API: 067-05276  
Date: 4/5/2022



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from from the northeastern corner facing southward. Dense Russian thistle debris needs to be removed and properly disposed of.



Photo 3. View of the northern project area from the northeastern corner facing westward.



Photo 4. View of reference area comprised of open grass field, with scattered rubber rabbitbrush and sagebrush shrubs, and western wheatgrass.