

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GM /13-33

Location ID: 323902



Photo #6369 from entrance to location.



Photo #6370 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GM /13-33

Location ID: 323902



Photo #6371 from entrance to location.



Photo #6372 Vent pipe on tank open ended.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GM /13-33

Location ID: 323902



Photo #6373 Loadline open ended.