

Inspection Photos

April 04, 2022

Operator: TEP Rocky Mountain- #96850

Location ID: 335481

Location Name: Jolley-66S91W /20NWNE

Inspection Document #: 702800122

Garfield County, CO

NWNE Section 20 T6S R91W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Jolley-66S91W /20NWNE
Location ID: 335481



Photo 1. Photo taken from the Location entrance facing south shows an overview of the Location and the lack of signage at the entrance.

Inspection Photos
Location Name: Jolley-66S91W /20NWNE
Location ID: 335481

4/4/22
+39.520341,-107.577231



Photo 2. Photo taken from the Location entrance facing south shows an overview of the Location and the lack of stabilization BMPs as is evidenced by the presence of ruts.

Inspection Photos
Location Name: Jolley-66S91W /20NWNE
Location ID: 335481



Photo 3. Photo taken from the north of the Location facing southwest shows interim areas colonized by perennial grasses.



Photo 4. Photo taken from the north of the Location facing southeast shows interim areas colonized by perennial grasses.

