

# Inspection Photos

API: 055-06146

Operator: PETROGLYPH OPERATING CO

Inspection Date: 4/6/2022



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06146 | Date: 4/6/2022

## Inspection Photos



**Photo 1.** Facing northwest along the access road. There is an erosion channel along the road that needs to be repaired and stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06146 | Date: 4/6/2022

## Inspection Photos



**Photo 2.** Facing northwest toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06146 | Date: 4/6/2022

## Inspection Photos



**Photo 3.** Facing southwest at the location which is stabilized with vegetation cover.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06146 | Date: 4/6/2022

## Inspection Photos



**Photo 4.** Facing southwest at the location which is stabilized with vegetation cover. Center of the location contains graveled area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06146 | Date: 4/6/2022