



Inspection Photos
Location Name: Pine Ridge Federal C1-W
Location ID: 315979
Spill/Release ID: TBD
Inspection Date: April 5, 2022

Aerial view of the location. The tank battery is in the green area and the apparent pit is in the red area.



Inspection Photos
Location Name: Pine Ridge Federal C1-W
Location ID: 315979
Spill/Release ID: TBD
Inspection Date: April 5, 2022

Location sign.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
Location Name: Pine Ridge Federal C1-W
Location ID: 315979
Spill/Release ID: TBD
Inspection Date: April 5, 2022

Tank battery where the spill/release occurred looking north. Note the apparent fluids present on the exterior of eastern tanks.

Apr 5, 2022 3:00:
+40.2123N -108.2





Inspection Photos

Location Name: Pine Ridge Federal C1-W

Location ID: 315979

Spill/Release ID: TBD

Inspection Date: April 5, 2022

Potentially impacted material within and on the exterior of the the tank battery secondary containment structure (southeast corner).



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources



Apr 5, 2022 3:03:
+40.2125N -108.2

Inspection Photos

Location Name: Pine Ridge Federal C1-W

Location ID: 315979

Spill/Release ID: TBD

Inspection Date: April 5, 2022

**Potentially impacted material
within the tank battery secondary
containment structure (southeast
corner).**



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources



Apr 5, 2022 3:00:
+40.2125N -108.2

Inspection Photos

Location Name: Pine Ridge Federal C1-W

Location ID: 315979

Spill/Release ID: TBD

Inspection Date: April 5, 2022

Potentially impacted material within the tank battery secondary containment structure (looking north).



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources



Inspection Photos
Location Name: Pine Ridge Federal C1-W
Location ID: 315979
Spill/Release ID: TBD
Inspection Date: April 5, 2022

Potentially impacted material within the tank battery secondary containment structure (northeast corner). Note the potentially impacted absorbent pads located with the tank batter secondary containment structure.





Inspection Photos
Location Name: Pine Ridge Federal C1-W
Location ID: 315979
Spill/Release ID: TBD
Inspection Date: April 5, 2022

East side of the tank battery secondary containment structure. Note the potential impacts on the exterior of the secondary containment structure where fluids had escaped and the potentially impacted absorbent pad.





Inspection Photos
Location Name: Pine Ridge Federal C1-W
Location ID: 315979
Spill/Release ID: TBD
Inspection Date: April 5, 2022

East side of the tank battery secondary containment structure. Note the potential impacts on the exterior of the secondary containment structure where fluids had escaped and the potentially impacted absorbent pad in what appears to be stormwater.

Apr 5, 2022 3:03:
+40.2126N -108.2





Inspection Photos

Location Name: Pine Ridge Federal C1-W

Location ID: 315979

Spill/Release ID: TBD

Inspection Date: April 5, 2022

Northeast corner of the tank battery secondary containment structure. Note the potential impacts on the exterior of the secondary containment structure where fluids had escaped and the potentially impacted absorbent pads.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources



Inspection Photos
Location Name: Pine Ridge Federal C1-W
Location ID: 315979
Spill/Release ID: TBD
Inspection Date: April 5, 2022

Northwest corner of the tank battery secondary containment structure. Note the potential impacts on the exterior of the secondary containment structure where fluids had escaped.



Inspection Photos
Location Name: Pine Ridge Federal C1-W
Location ID: 315979
Spill/Release ID: TBD
Inspection Date: April 5, 2022

Northwest corner of the tank battery secondary containment structure. Note the potential impacts and the potentially impacted absorbent pads.



Inspection Photos
Location Name: Pine Ridge Federal C1-W
Location ID: 315979
Spill/Release ID: TBD
Inspection Date: April 5, 2022

Potential impacts around the pump building located north of the tank battery. The same building can be seen in the top left corner of the previous photo.



Inspection Photos

Location Name: Pine Ridge Federal C1-W

Location ID: 315979

Spill/Release ID: TBD

Inspection Date: April 5, 2022

Northeast corner of the Pine Ridge Federal C1-W location. Note the potential impacts and the potentially impacted absorbent pads in what appears to be stormwater. The tank battery secondary containment structure and the pump building can be seen in the background of the photo.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources



Inspection Photos

Location Name: Pine Ridge Federal C1-W

Location ID: 315979

Spill/Release ID: TBD

Inspection Date: April 5, 2022

Northeast corner of the Pine Ridge Federal C1-W location. Note the potential impacts and the potentially impacted absorbent pads in what appears to be stormwater.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources



Inspection Photos
Location Name: Pine Ridge Federal C1-W
Location ID: 315979
Spill/Release ID: TBD
Inspection Date: April 5, 2022

Northeast corner of the Pine Ridge Federal C1-W location. Note the potential impacts and the potentially impacted absorbent pads (left side) in what appears to be stormwater.





Apr 5, 2022 3:05:
+40.2128N -108.2

Inspection Photos

Location Name: Pine Ridge Federal C1-W

Location ID: 315979

Spill/Release ID: TBD

Inspection Date: April 5, 2022

**North side of the Pine Ridge
Federal C1-W location. Note the
potential impacts and the residual
impact ring.**



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources



Apr 5, 2022 3:06:
+40.2129N -108.2

Inspection Photos

Location Name: Pine Ridge Federal C1-W

Location ID: 315979

Spill/Release ID: TBD

Inspection Date: April 5, 2022

**North side of the Pine Ridge
Federal C1-W location. Note the
potential impacts and the residual
impact ring.**





Apr 5, 2022 3:04:
+40.2128N -108.2

Inspection Photos
Location Name: Pine Ridge Federal C1-W
Location ID: 315979
Spill/Release ID: TBD
Inspection Date: April 5, 2022

Potentially impacted absorbent pads blown off the location.





Apr 5, 2022 3:10:
+40.2126N -108.2

Inspection Photos
Location Name: Pine Ridge Federal C1-W
Location ID: 315979
Spill/Release ID: TBD
Inspection Date: April 5, 2022

Potentially impacted absorbent pads blown off the location.





Inspection Photos
Location Name: Pine Ridge Federal C1-W
Location ID: 315979
Spill/Release ID: TBD
Inspection Date: April 5, 2022

Potentially impacted absorbent pads blown off the location.





Apr 5, 2022 3:08:
+40.2126N -108.2

Inspection Photos
Location Name: Pine Ridge Federal C1-W
Location ID: 315979
Spill/Release ID: TBD
Inspection Date: April 5, 2022

Apparent pit on location.





Apr 5, 2022 3:08:
+40.2126N -108.2

Inspection Photos
Location Name: Pine Ridge Federal C1-W
Location ID: 315979
Spill/Release ID: TBD
Inspection Date: April 5, 2022

Apparent pit on location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Pine Ridge Federal C1-W
Location ID: 315979
Spill/Release ID: TBD
Inspection Date: April 5, 2022

Mislabeled tank.

