

Inspection Photos
Location Name: McCallum 150
Location ID: 324713



Photo 1. Overview of location taken facing south.



Photo 2. Stained soil at wellhead.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources