

**Inspection Photos**  
**Location Name: Klaenhammer 1**  
**Location ID: 312861**



**Photo 1. Overview of location taken facing south.**



**Photo 2. Stained soil in pit bottom.**

**Inspection Photos**  
**Location Name: Klaenhammer 1**  
**Location ID: 312861**



**Photo 3. Unmarked risers at wellhead.**



**Photo 4. Unmarked risers adjacent to pit.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources