

**Inspection Photos**  
**Location Name: Amoco-Federal 21-1**  
**Location ID: 312970**



**Photo 1. Overview of location taken facing northwest.**



**Photo 2. East tank missing label. Pit 1 of 2 on east side of tank battery.**



**Inspection Photos**  
**Location Name: Amoco-Federal 21-1**  
**Location ID: 312970**



**Photo 3. Stained soil at wellhead. Chemical container with no secondary containment.**



**Photo 4. Spill at pump jack.**



**Inspection Photos**  
**Location Name: Amoco-Federal 21-1**  
**Location ID: 312970**



**Photo 5. Spill at pump jack.**



**Photo 6. Spill at pump jack.**



**Inspection Photos**  
**Location Name: Amoco-Federal 21-1**  
**Location ID: 312970**



**Photo 7. Free fluid in spill at pump jack.**



**Photo 8. Stained soil at pump jack exhaust.**

**Inspection Photos**  
**Location Name: Amoco-Federal 21-1**  
**Location ID: 312970**



**Photo 9. Chemical container at entrance has blown over and become debris.**



**Photo 10. Example of absorbent pad blowing off location.**

