

**Inspection Photos**  
**Location Name: UPRR 43 PAN AM G 1**  
**Location ID: 317915**



**Pic 1 wellhead, plunger lift.**



**Pic 2 pump jack equipment on location needs to be removed.**