

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/06/2022

Submitted Date:

04/07/2022

Document Number:

689501355

FIELD INSPECTION FORM

Loc ID 472056 Inspector Name: Brown, Kari On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1775 SHERMAN STREET - STE 3000
City: DENVER State: CO Zip: 80203

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	ALL INSPECTIONS
, Spills&Remediations		COGCCSpillRemediation@pdce.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
481531	SPILL OR RELEASE	CL	02/11/2022		-	HL 26-1	EI

General Comment:

This is an environmental inspection of Remediation Spill ID 481531(CL)/Remediation Project No 21292. Any corrective actions from previous inspections that have not been addressed are still applicable.

There were no operator or contract environmental personnel on location at the time of this field inspection.

Photos attached to document site conditions

Inspected Facilities

Facility ID: 481531 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: Excavation area has been backfilled and no indication of E&P waste remains on site. Final reclamation has been initiated on location.

Corrective Action: Submit an updated Supplemental Form 27 (Rem No 21292) for the remediation of this release. Date: 05/06/2022

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403009089	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5718440
689501370	Site photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5718434