

Inspection Photos

ROHR #09-10 Big Pit

Operator: PETROGLYPH OPERATING CO

Inspection Date: 4/6/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06165 | Date: 4/6/2022

Inspection Photos



Photo 1. Drone aerial photo facing south toward reclaimed ROHR #09-10 Big Pit.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06165 | Date: 4/6/2022

Inspection Photos



Photo 2. Drone aerial photo facing southeast toward reclaimed ROHR #09-10 Big Pit.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06165 | Date: 4/6/2022

Inspection Photos



Photo 3. Drone aerial photo facing north toward reclaimed ROHR #09-10 Big Pit.



Inspection Photos



Photo 4. Drone aerial photo facing northwest toward reclaimed ROHR #09-10 Big Pit.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06165 | Date: 4/6/2022

Inspection Photos



Photo 5. Facing toward the reclaimed area located northeast of the Big Pit. There is debris and leftover pipe supplies that remain shown at red arrows.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06165 | Date: 4/6/2022

Inspection Photos



Photo 6. There is still debris that remains at the northeast side of the location that has not been removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06165 | Date: 4/6/2022

Inspection Photos



Photo 7. Located at the northeast corner of the location is pipe and leftover supplies that has not been removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06165 | Date: 4/6/2022

Inspection Photos



Photo 8. There still appears to be some areas that have not established adequate vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06165 | Date: 4/6/2022