

Inspection Photos  
Operator: Simcoe  
API: 067-07126  
Date: 4/8/2022



Photo 1. View of the project area from the well pad entrance facing center.





Photo 2. View of the northwestern project area from the western corner facing northeastward. Revegetation is progressing with western wheatgrass, smooth brome, and sand dropseed.



Photo 3. View of the southwestern project area from the western corner facing southeastward.





Photo 4. View of reference area comprised of ponderosa pine woodland with understory of gambel oak, James galleta, western wheatgrass, and sandberg bluegrass.