

Inspection Photos  
Operator: Simcoe  
API: 067-08648  
Date: 4/8/2022



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation is progressing with western wheatgrass and smooth brome.





Photo 3. View of the western project area from the northwestern corner facing southward.





Photo 4. View of reference area comprised of ponderosa pine woodland with understory of gambel oak, James galleta, western wheatgrass, black sagebrush, and sandberg bluegrass.