

# Inspection Photos

API: 071-07991

Operator: OGRIS OPERATING LLC

Inspection Date: 4/21/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-07991 | Date: 4/21/2022

## Inspection Photos



**Photo 1.** Facing southeast toward the wellsite.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07991 | Date: 4/21/2022



## Inspection Photos



**Photo 3.** There is a dripping PW leak near the tank that needs repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07991 | Date: 4/21/2022

## Inspection Photos



**Photo 4.** There is oil stained soils around the engine skid that needs to be cleaned up and properly disposed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07991 | Date: 4/21/2022