

Inspection Photos

API: 071-07944

Operator: OGRIS OPERATING LLC

Inspection Date: 4/21/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07944 | Date: 4/21/2022

Inspection Photos



Photo 1. Facing west at the road in the canyon bottom.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07944 | Date: 4/21/2022

Inspection Photos



Photo 2. Facing west along the road. Soil material is graded off the road which will not allow drainage toward the culverts. The road is not stabilized and maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07944 | Date: 4/21/2022

Inspection Photos



Photo 3. Facing west along the road. Soil material is graded off the road which will not allow drainage toward the culverts. The road is not stabilized and maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07944 | Date: 4/21/2022

Inspection Photos



Photo 4. Facing toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07944 | Date: 4/21/2022