

Inspection Photos

API: 071-09236

Operator: OGRIS OPERATING LLC

Inspection Date: 4/21/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09236 | Date: 4/21/2022

Inspection Photos



Photo 1. Facing northeast toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09236 | Date: 4/21/2022

Inspection Photos



Photo 2. Facing toward the engine skid. Fluids were removed from the skid and gravel was placed around the skid but it does not seem stained soils were cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09236 | Date: 4/21/2022

Inspection Photos



Photo 3. There is stained soils visible underneath the gravel.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09236 | Date: 4/21/2022