

Inspection Photos
Location Name: Meyers F-1
Location ID: 318940



Photo 1 - Tank Flowline Risers

Photo 2 – Flowlines at Heater Treater Area

Inspection Photos
Location Name: Meyers F-1
Location ID: 318940



Photo 3 – Flowlines at Heater Treater Area

Photo 4 – Well has been Cut and Capped, buried

Inspection Photos
Location Name: Meyers F-1
Location ID: 318940



Photo 5 – Sub Base, Gear Box and Counter Weights

Photo 6 – Engine Area

Inspection Photos
Location Name: Meyers F-1
Location ID: 318940



Photo 7 – Tank Battery Sign



Photo 8 – Overview looking Southeast

Inspection Photos
Location Name: Meyers F-1
Location ID: 318940



Photo 9 – Overview Looking East