

**Inspection Photos**  
**Location Name: Perrin 1-10H**  
**Location ID: 424875**



**Photo 1 – Tank Battery**



**Photo 2 – Tank Battery Sign**



**Inspection Photos**  
**Location Name: Perrin 1-10H**  
**Location ID: 424875**



**Photo 3 – NFPA Label has faded**



**Photo 4 – Heater Treater and Gas Meters**



**Inspection Photos**  
**Location Name: Perrin 1-10H**  
**Location ID: 424875**




**Photo 5 – ECD and Gas Meters**



**Photo 6 – Valve now in Closed Position**



**Inspection Photos**  
**Location Name: Perrin 1-10H**  
**Location ID: 424875**



**Photo 7 – Valve now in the Closed Position**



**Photo 8 – Pumping Unit**