

Inspection Photos

Location Name: CAERUS PICEANCE LLC PUCKETT-66S97W /24NWSW

Location ID: 335527



Photo #6531 from entrance to location.



Photo #6532 Unused equipment.

Inspection Photos

Location Name: CAERUS PICEANCE LLC PUCKETT-66S97W /24NWSW

Location ID: 335527



Photo #6533 Flowline heating insulation open ended.



Photo #6534 Loadline open ended.