

Inspection Photos

Location Name: N. Parachute WF K22 596 Pad & Remediation Project

Location ID: #335648 & Remediation Project # 12690

Inspection Date: April 22, 2022



Photo #1 – Sign at pad entrance.



Photo #2 – Mobile separator unit observed in southwest corner of pad.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: N. Parachute WF K22 596 Pad & Remediation Project

Location ID: #335648 & Remediation Project # 12690

Inspection Date: April 22, 2022



COGCC Field Inspection
39.5989, -108.15961, 6454.9ft, 42°
04/22/2022 10:15:39 AM

Photo #3 – SVE wells related to ongoing Remediation Project #12690.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources