

Inspection Photos

4/22/2022

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 335676

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 335676



Photo 1: Photo shows two (2) mobile separator units on the south end of the Location.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 335676



Photo 2: Continued from photo 1. Photos show the containment BMPs at the mobile separator units are inadequate to contain a spill.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 335676



Photo 3: Photo shows capacity labeling is missing from the produced water tank on the southeast end of the Location.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 335676



April 22, 2022
39.62781643N 108.15611295W

Photo 4: Photo taken from the interim areas on the north end of the Location. Photo shows revegetation in these areas is progressing towards a uniform desirable perennial vegetative cover.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 335676



Photo 5: Photos 5-9 taken from the interim areas on the east end of the Location. Photos examples showing stormwater and erosion control measures to minimize erosion and degradation are missing or insufficient; erosion evident. Photos also examples showing areas on the east end of the Location where desirable vegetative germination, or uniform vegetative establishment was not observed, or observed to not be progressing towards a uniform standard.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 335676



April 22, 2022
39.62750718N 108.15528503W

Photo 6: See comments under photo 5.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 335676



Photo 7: See comments under photo 5.



Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 335676



Photo 8: See comments under photo 5.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 335676



Photo 9: See comments under photo 5.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 335676



Photo 10: Photo taken from the interim areas on the east end of the Location. Photo shows Operator appears to have previously implemented a tackfier or hydromulch, however control has not been maintained in a proper functioning condition.