

Final Reclamation Inspection

April 22, 2022

Operator: OVERLAND RESOURCES LLC - #19035

Location ID: 320755

Inspection Document #: 697503883

Arapahoe County, CO

NESE Section 30 T5S R62W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BEICHLE #30-43
Location ID: 320755



Photo 1. Google Earth aerial imagery from 6/24/1993 illustrates the well location, access road and the associated tank battery during active operations. Photo illustrates a pit along the northern location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697503883

Inspection Photos
Location Name: BEICHLE #30-43
Location ID: 320755



Image U.S. Geological Survey

Photo 2. Google Earth aerial imagery from 9/29/1999 illustrates an area adjacent to and north of the pit that appears to be impacted. Note- during the 4/22/2022 inspection, vegetation was sparse or bare soil in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697503883



Photo 3. Google Earth aerial imagery from November 2019 illustrates the approximate area of disturbance related to the Beichle #30-43 location.

Inspection Photos
Location Name: BEICHLE #30-43
Location ID: 320755



04.22.2022 09:30

Photo 4. Photo taken from the northern area of disturbance, facing Southeast. Photo illustrates an area that appears to be impacted by a potential produced water spill, as there is no vegetative growth.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697503883

Inspection Photos
Location Name: BEICHLE #30-43
Location ID: 320755



Photo 5. Photo taken from the former pit area, facing East. See comments under Photo 4.



Photo 6. Photo taken from the former pit area, facing South. See comments under Photo 4.

Inspection Photos
Location Name: BEICHLE #30-43
Location ID: 320755



Photo 7. Photo taken from the southern tank battery area, facing North. Photo illustrates some vegetative growth but it is not reflective of reference area levels.



Photo 8. Photo taken from a portion of the access road, facing East. Photo illustrates access road is evident because it was not contoured. There is some desirable vegetation observed but it is not reflective of reference area levels.

Inspection Photos
Location Name: BEICHLE #30-43
Location ID: 320755



Photo 9. Photo taken from the well location, facing Northwest. Photo illustrates a bare patch where the wellhead was located.



Photo 10. Photo taken from the well location, facing North. Well location is progressing towards vegetative standards but it is not reflective of reference area levels. It appears the seed mix used was an introduced mix of crested wheatgrass and smooth brome.



Inspection Photos
Location Name: BEICHLE #30-43
Location ID: 320755



Photo 11. Reference photo taken southwest of the well location, facing West. Some of the reference area grass species consist of: western wheatgrass, sand dropseed, prairie sandreed and smooth brome.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697503883