

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/22/2022

Submitted Date:

04/25/2022

Document Number:

697503883**FIELD INSPECTION FORM**Loc ID 320755 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 19035Name of Operator: OVERLAND RESOURCES LLCAddress: SUITE C18 PMB 440City: GREENWOOD State: CO Zip: 80121**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		kelly.rosenberg@state.co.us	
		greg@overlandresourcesllc.com	
		cpandolfo@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
204814	WELL	PA	03/04/2004	OW	005-06899	BEICHLE 30-43	RI

General Comment:This is a Final Reclamation inspection at the request of COGCC Enforcement.

Inspected Facilities									
Facility ID:	204814	Type:	WELL	API Number:	005-06899	Status:	PA	Insp. Status:	RI

--

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment: Based on historic aerial imagery and field observations, there appears to be areas impacted from the pit that could be associated with produced water. The northern half of the tank battery and areas adjacent to the northern tank battery are exposed bare soil with no vegetation. Refer to the attached inspection photos.

Corrective Action: At a minimum, Operator shall conduct sampling and analysis of soil pursuant to rules 915.b and 915.e.(2)D to determine the horizontal and vertical extent of inorganic pollutants that may be inhabiting vegetative growth. Completion of delineation will be reported on a Form 27. Operator shall perform sampling and analysis before conducting final reclamation activities. There is no corrective action date since this is an enforcement matter.

Date: _____

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% **Fail** Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:

Corrective Action:	<p>It appears the Operator failed to respond to the previous final reclamation corrective action inspection from 2017 (Doc.# 682501916). There is no indication that further reclamation activities have been performed.</p> <p>The location does not comply with final reclamation rules. There is exposed soil/insufficient vegetative cover throughout the tank battery (and north of the tank battery), access road and well location. The access road has not been contoured but desirable vegetation has started to establish and stabilize the access road.</p>	Date 05/31/2017
	<p>After the Operator has fulfilled the requirements of Rule 915.b and 915.e.(2)D, then Operator shall comply with Rule 1004. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.</p>	
Overall Final Reclamation Fail Well Release on Active Location <input type="checkbox"/> Multi-Well Location <input type="checkbox"/>		

COGCC Comments

Comment	User	Date
Operator should reference the COGCC Operator Guidance for Rule 915.b- Soil Suitability for Reclamation regarding sampling and analysis of inorganics.	binschusc	04/25/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697503884	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5734810