

# Final Reclamation Inspection

April 19, 2022

Operator: HIGHPOINT OPERATING CORPORATION- #10071

Location ID: 319062

Inspection Document #: 697503891

Weld County, CO

NESE Section 28 T1N R64W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation**  
**Commission**

Department of Natural Resources



**Photo 1.** Google Earth aerial imagery from 6/9/2017 during active operations illustrates the well location, access road, and associated offsite tank battery.

Inspection Photos  
Location Name: MANDY #43-28  
Location ID: 319062



**Photo 2.** Photo taken from the southern portion of the associated tank battery, facing North. Photo illustrates not all gravel has been removed and there was no observed crop growth much of the tank battery.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 697503891

Inspection Photos  
Location Name: MANDY #43-28  
Location ID: 319062



**Photo 3.** Photo taken from the central portion of the associated tank battery, facing North. See comments under Photo 2.

Inspection Photos  
Location Name: MANDY #43-28  
Location ID: 319062



**Photo 4.** Photo taken from the northern portion of the associated tank battery, facing South. See comments under Photo 2.

Inspection Photos  
Location Name: MANDY #43-28  
Location ID: 319062



**Photo 5.** Photo taken from the northern portion of the associated tank battery, facing Northeast. See comments under Photo 2.

