

Inspection Photos

API: 061-06397

Operator: BERRY ENERGY INC

Inspection Date: 4/25/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06397 | Date: 4/25/2022

Inspection Photos



Photo 1. Facing southwest at the former tank battery location. Soils remain mostly bare of vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06397 | Date: 4/25/2022

Inspection Photos



Photo 2. Facing south at abandoned wellsite location. Soils remain bare of vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06397 | Date: 4/25/2022

Inspection Photos



Photo 3. Facing northwest at abandoned wellsite location. Soils remain bare of vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06397 | Date: 4/25/2022

Inspection Photos



Photo 4. View of groundcover at the location shows no vegetation establishment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06397 | Date: 4/25/2022

Inspection Photos



Photo 5. Facing south toward the surrounding undisturbed pasture which consists of Blue grama, Sand drop seed, among other native species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06397 | Date: 4/25/2022