

Inspection Photos

API: 061-06084

Operator: CHEMCO INC

Inspection Date: 4/25/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06084 - Date: 4/25/2022

Inspection Photos



Photo 1. Drone aerial photo facing down toward the plugged and abandoned well site. The area around the abandoned site is bare of vegetation which indicates impacted soils from oil and gas operations.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06084 - Date: 4/25/2022

Inspection Photos



Photo 2. Facing north toward the abandoned well site. The location is bare of vegetation on approximately 150'x120' area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06084 - Date: 4/25/2022

Inspection Photos



Photo 3. Center of the location facing south. The area around the abandoned site is bare of vegetation which indicates impacted soils from oil and gas operations.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06084 - Date: 4/25/2022