

Inspection Photos

API: 061-05145

Operator: WESTERN OPERATING COMPANY

Inspection Date: 4/25/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05145 - Date: 4/25/2022

Inspection Photos



Photo 1. Facing south toward the location. There are areas at the location that are bare of vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05145 - Date: 4/25/2022

Inspection Photos



Photo 2. Facing north toward the location. There are areas at the location that are bare of vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05145 - Date: 4/25/2022

Inspection Photos



Photo 3. Ground cover at center of the location. There is darkened soils in this area with a hydrocarbon odor. Contaminated soils need to be properly removed and disposed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05145 - Date: 4/25/2022

Inspection Photos



Photo 4. The powerline used for operating the well dead ends at the location and the entire unused portion of the powerline must be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05145 - Date: 4/25/2022