

## Inspection Photos

Location Name: CAERUS PICEANCE LLC DAYBREAK-67S96W /36NENE

Location ID: 334089



Photo #6566 from entrance to location.



Photo #6567 from entrance to location.

## Inspection Photos

Location Name: CAERUS PICEANCE LLC DAYBREAK-67S96W /36NENE

Location ID: 334089



**Photo #6568 Stained soils inside tank containment.**